


NOTES:

- 1. REPLACEMENT OF HMA SHALL MATCH EXST. DEPTH (4—INCH MINIMUM), OR OTHERWISE SPECIFIED ON PLANS. IN NO CASE SHALL THICKNESS BE LESS THAN THAT SHOWN ON STANDARD DETAIL 4200—1.
- 2. REFERENCE TECHNICAL SPEC. SECTION 2400, 4200 AND 4220.



TRENCH CAP

REV: DEC. 2016
SCALE: NTS
DET No.
3800-5